


# INSTRUCTIONS

## 48" MagnaStrip™ on End Cap Side Rail



1. Thread tie-bands through front of MagnaStrip as shown.
2. Place MagnaStrip on end cap side rail and connect the tie-bands through slots of side rail pull tight and trim off excess tie-bands.
3. Install peg hook with scan plate at top of MagnaStrip, install rest of peg hooks to accommodate product.
4. Place UPC label on scan plate, load product.



 **TMSHEA**  
PRODUCTS

1950 Austin Drive • Troy, Michigan 48083  
800-992-5233 • 248-589-3272 • Fax 248-589-1535  
Email: [hq@tmshea.com](mailto:hq@tmshea.com) • [www.tmshea.com](http://www.tmshea.com)





